

U. S. ENVIRONMENTAL PROTECTION AGENCY  
REGION IV, ATHENS, GEORGIA

3.8 3569

MEMORANDUM

3 8

0689

SOUTH

MAY 11 1992

SUBJECT: Preliminary Site Characterization Summary Report,  
RI/FS; Olin Corporation, McIntosh Plant;  
McIntosh, Washington County, Alabama;  
ESD Project No. 92E-401.

BRANCH

FROM: Roger E. Carlton, Environmental Engineer  
Hazardous Waste Section  
Environmental Compliance Branch  
Environmental Services Division

*Roger E. Carlton*

TO: Cheryl W. Smith, Remedial Project Manager  
AL/GA/MS Remedial Section  
South Superfund Remedial Branch  
Waste Management Division

THRU: William R. Bokey, Chief  
Hazardous Waste Section  
Environmental Compliance Branch  
Environmental Services Division

*William R. Bokey*

ESD has reviewed the Preliminary Site Characterization Summary Report, RI/FS; Olin Corporation, McIntosh Plant, McIntosh, Washington County, Alabama and the following comments are for your consideration:

1. Page 45, paragraph 1, line 5 "int he"

Comment: This should be "in the".

2. Table 6, Table 7, and Table 8. Organics and Inorganics in Ground Water.

Comment: On page 30 reference is made to the use of Acrylic and Teflon® bailers to collect ground water samples. It should be noted which type of bailer was used in which well. This would assist in evaluating the possible effects on the samples where Acrylic was used.

2. Table 12, Table 13, and Sample Data Sheets, Volume II . Inorganics.

Comment: The aluminum data was omitted. If aluminum irrigation pipe was used (Page 42) to collect the subsurface soil and sediment core samples, the results of the aluminum analysis should be included.

If you have any questions, contact me at Commercial or FTS (706) 546-3351.

cc: Bokey/Hall  
Knight